
Rewilding Efforts through the San Antonio River Authority





Otilla Dam











Fish Movement







Mussel Populations







Otilla Dam Removal/Modification

USFWS National Fish Passage Program grant proposal

SAWS Dam Assessment

 Network for Engineering With Nature Restoration proposal







Freshwater Mussel Reintroduction into the Upper San Antonio River

Chris Vaughn
San Antonio River Authority
cvaughn@sariverauthority.org









Committed to Safe, Clean, Enjoyable Creeks and Rivers.

Holistic Mussel Project









U. S. GEOLOGICAL SURVEY




What even is a mussel?

- What do they do?
- Why do we care?
 - Ecosystem services
 - They were here first

















Weight (Δ %) Overtime





Mussel Toxicology Research

- Concerns for introduction in an urban environment
- Stormwater analysis in Mission Reach
- Highest NH₃N value 0.48 mg/L
- Highest Cu value 74.0 μg/L







Mussel Toxicology Research

- Concerns for introduction in an urban environment
- Stormwater analysis in Mission Reach





△ Median daily statistic (27 years) — Period of approved data — Discharge



△ Median daily statistic (27 years) — Period of approved data

— Discharge



















Boulder Clay Cobble Concrete gravel

Deployment Locations In Original Position at end of Season

		0.00		The second secon	The second secon
	End of Season	Total at	Percent of End of	Percent of Total	Percent at End of Season
Site 1	Orig Pos	Season Start	Season Total Orig Pos	Season Start OP	of Start Orig Pos
Boulder	20	51	51.3%	26%	39.2%
Gravel	2	14	5.1%	7%	14.3%
Clay	2	10	5.1%	5%	20.0%
Cobble	15	52	38.5%	26%	28.8%
	20	107			

127






- Deployment Locations
- Rescan points after movement
- → Major movement trends


Storm Size		1500 cfs	3000 cfs	3700 cfs	100 cfs
Distance Traveled	Count for Full Season	4/27/2022	5/7/2022	7/6/2022	8/18/2022
< 2.5m	39	18	13	1	7
2.5m > x > 5m	30	7	9	6	8
5m > x > 10m	30	2	8	11	9
<10m	17	1	1	9	6
Average Dist Traveled	7.43	2.6	3.74	17.35	6.8













Committed to Safe, Clean, Enjoyable Creeks and Rivers.

















Culebra Creek Tributary F

Erosion, destabilized banks, loss of riparian habitat







Erosion migrating upstream







Restoration Activities



Bank Restoration



Log Rollers for Energy Disipation



Restored Streambanks





East Salitrillo Creek in 2011





Restoration Activities



- Bank restoration with geolifts
- Instream structures to sculpt flows





Pre and Post Restoration Comparison

2010

